

National Dam
Inspection Program



Phase I
Inspection
Report for
June 1979 **MATILIJA
DAM**

Prepared for Department of the Army
The Corps of Engineers
Sacramento District

By State of California
The Resources Agency
Department of
Water Resources
Division of Safety
of Dams

Incl 1



DEPARTMENT OF THE ARMY
SACRAMENTO DISTRICT, CORPS OF ENGINEERS
650 CAPITOL MALL
SACRAMENTO, CALIFORNIA 95814

GJD
4651

REPLY TO
ATTENTION OF
SPKED-D

17 August 1979

Mr. A. P. Stokes
Director of Public Works
and Engineering Manager
Ventura County Flood Control District
800 South Victoria Avenue
Ventura, CA 93309

Dear Mr. Stokes:

Inclosed is one copy of Phase I Investigation Report for Matilija Dam prepared for the Sacramento District, U. S. Army Corps of Engineers, by the State of California, Department of Water Resources, in accordance with the National Dam Inspection Act.

One copy of this report has also been sent to Governor Brown.

Under provisions of the Freedom of Information Act, these reports will be subject to release upon request after receipt by you or your representatives.

Under the National Dam Inspection Program the State is required to keep me informed of what actions are taken pursuant to the recommendations of this report. Your cooperation with the State will be greatly appreciated.

Sincerely,

PAUL F. KAVANAUGH
Colonel, CE
District Engineer

1 Incl
As stated

CF: w/o Incl
Mr. James J. Doody
Chief, Division of Safety of Dams
Dept of Water Resources, P.O. Box 388
Sacramento, CA 95802

**National Dam
Inspection Program**

**Phase I
Inspection
Report for**

**MATILIJA
DAM**

June 1979

**Prepared for:
Department of the
Army
The Corps of
Engineers
Sacramento District**



REF000000065

**By:
State of California
The Resources Agency
Department of
Water Resources
Division of
Safety of Dams**



NATIONAL PROGRAM FOR INSPECTION OF DAMS
PHASE I INSPECTION REPORT
FOR
MATILIJA DAM
VENTURA COUNTY, CALIFORNIA


AUTHORIZATION: The preparation of this report was authorized by the National Dam Inspection Act, Public Law 92-367.

BRIEF ASSESSMENT: This report has been reviewed by this office and I concur with your assessment that Matilija Dam appears to be safe. I also agree with recommendations for monitoring behavior of the dam.

This conclusion is based on information presented in the report which includes past investigations initiated by the owner as well as the investigations done for this report, and the maintenance done by the owner as a result of those investigations.

In light of the detailed stability and hydrologic studies performed, further in-depth studies and a Phase II-type report are not required.

APPROVAL: This report creates no liability on the United States, its officers or employees. The owner and operator continue to be solely responsible for all legal duties, obligations, or liabilities associated with the ownership or operation of the dam.


PAUL F. KAVANAUGH
Colonel, CE
District Engineer

DATE: 30 July 79

NATIONAL DAM INSPECTION PROGRAM
PHASE I REPORT
MATILIJA DAM

BRIEF ASSESSMENT

The Phase I investigation of Matilija Dam has been completed. The two primary conclusions of the investigation are that alkali-aggregate reaction is gradually destroying the dam and that the reservoir is gradually filling with erosional depositions from the drainage area.

The owner is aware of, and has evaluated and taken action as a result of these problems. The owner has employed the Bechtel Corporation and the International Engineering Company to evaluate the safety of the dam. In 1965 a 280-foot long by 30-foot deep section of the dam was removed as a result of concrete deterioration caused by reactive aggregate. Additional concrete also was removed in 1977-78 at the ends of the notch cut in 1965. As modified, the dam is safe for the near term future.

The principal recommendations of the report are that:


- the dam should continue to be kept under close observation to detect changes beyond the bounds of those anticipated when making the foregoing studies, and
- periodic testing of the concrete should be continued, including strength, petrographic and soniscopic tests at intervals of 5 years or less as recommended in the August 1967 Bechtel Corporation Report "Review of Matilija Dam."

Those recommendations have been provided to the owner. The owner also has been requested to repair the intake riser of the dam. The owner has filed and received approval from the California Division of Safety of Dams for replacement of the intake riser; construction is scheduled for the fall of 1979.

We do not recommend further investigation of the dam at this time.

ENGINEERING CERTIFICATION

This report has been prepared under my direction as the professional engineer in direct responsible charge of the work, in accordance with the provisions of the Professional Engineers' Act of the State of California.


James J. Doody, Chief
Division of Safety of Dams
Registered C. E. No. 6500
Date: JUL 20 1979

State of California
The Resources Agency
DEPARTMENT OF WATER RESOURCES
Division of Safety of Dams

NATIONAL DAM INSPECTION PROGRAM

PHASE I REPORT

Dam	Matilija
State	California
County	Ventura
Stream	Matilija Creek
Tributary to	Ventura River
Owner	Ventura County Flood Control District

Report prepared under
the direction of

James J. Doody
Division Chief
RCE 6500

Under the supervision of

R. E. Stephenson
Supervising Engineer
RCE 11334

by

J. Fred Chaimson
Senior Engineer
RCE 12393

TABLE OF CONTENTS

	<u>PAGE</u>
1. INTRODUCTION	1-1
1.1 Authority	1-1
1.2 Purpose	1-1
1.3 Scope	1-1
2. DESCRIPTION OF PROJECT	2-1
2.1 Data Summary	2-1
a. General Data	2-1
b. Reservoir Data	2-1
c. Main Dam	2-1
d. Auxiliary Dams	2-1
e. Spillway	2-2
f. Outlets	2-2
2.2 General Description	2-2
a. Dam	2-2
b. Reservoir	2-2
c. Location	2-2
d. Outlet Works	2-9
e. Spillway	2-9
f. Size Classification	2-9
g. Hazard Classification	2-9
h. Ownership	2-9
i. Purpose	2-9
j. Operation Procedures	2-10
k. Watershed	2-10
l. Instrumentation and Monitoring	2-10
3. GENERAL HISTORY	3-1
4. ENGINEERING DATA	4-1
4.1 Geologic Conditions	4-1
a. Areal Geology	4-1
b. Regional Seismicity and Faulting	4-1
c. Foundation	4-7
d. Spillway	4-7
e. Data	4-7
4.2 Design	4-7
a. Structural	4-7
b. Hydrology and Hydraulics	4-7
4.3 Construction	4-8
4.4 Operation	4-8

National Dam Inspection Program
Phase I Report

MATILIJA DAM

1. INTRODUCTION

1.1 Authority

This evaluation is made under the authority of the National Dam Inspection Act, Public Law 92-367, August 8, 1972 and the contract executed between the United States of America (represented by the Sacramento District, United States Army Corps of Engineers) and the State of California (represented by the Department of Water Resources).

1.2 Purpose

The purpose of a Phase I investigation is to identify dams which may pose hazards to human life and property and to recommend additional investigation when required.

1.3 Scope

The Phase I investigation is primarily a review of records and a systematic visual inspection. Records considered include, where available, the plans and specifications under which the dam was built, exploration, testing and design reports leading to that design, evaluations, and the studies and reports made by and in the files of the State of California, Department of Water Resources, Division of Safety of Dams.

2. DESCRIPTION OF PROJECT

2.1 Data Summary

a. General Data

Owner	Ventura County Flood Control District
Stream	Matilija Creek
Location	5 miles northwest of Ojai
Purpose	Water Conservation (See Section 2.2 i.)
Drainage Area	55 square-miles
Year Completed	1949

b. Reservoir Data

Normal Pool Elevation	1,095
Normal Storage	1,800 acre-feet (see Section 5.3h)

c. Main Dam

Type	Concrete Arch
Dam Crest Elevation	1,138 feet
Freeboard	27 feet ¹
Height	163 feet
Length of Crest	620 feet
Thickness at Crest	8.0 feet
Volume	47,825 cubic yards

d. Auxiliary Dams

None

¹Distance from maximum design flood water surface to top of dam with spillway as notched in 1978.





Photo No. 2.1
View from operator's house.



Photo No. 2.2
View from left abutment.



Location Map



Approximate Drainage Area

VICINITY MAP
 Basic Map Reproduced by Permission of California
 State Automobile Association, Copywrite Owner



d. Outlet Works

There is a 48-inch sluice at the crown of the arch at Elevation 1,000.8 which is presently planned to be abandoned. A 36-inch outlet pipe near the left abutment at Elevation 1,025 discharges directly into the main of the Casitas Municipal Water District. A 36-inch butterfly valve on this line provides blowoff directly to the stream. Under construction (in July 1978) is another outlet (42 inches) just above the 36-inch outlet at Elevation 1042.5. This is expected to provide about 630 cfs capacity when construction is complete, including a new outlet riser.

e. Spillway

The spillway is a 360 foot-wide notch cut in the dam at Elevation 1,095. It is estimated to discharge the Probable Maximum Flood peak of 76,108 cfs with 16.0 feet of head.

f. Size Classification

The dam, with a maximum height of 120 feet and storage capacity of 1,800 feet, is classified by size as large in accordance with Table 1, Attachment A, of the contract (Section I-1) Recommended Guidelines for Safety Inspection of Dams (Reference 1).

g. Hazard Classification

The hazard classification is rated as "high" based on the indicated inundation of numerous houses and several county road bridges in the vicinity of Meiners Oaks and Live Oak Acres.

h. Ownership

The dam is owned by the Ventura County Flood Control District, 597 East Main Street, Ventura, California. The dam is operated under contract for the benefit of the Casitas Municipal Water District.

i. Purpose

The purpose for constructing the dam was water conservation and flood control. Because of the small size of the reservoir it has negligible effect on large floods.

j. Operation Procedures

The following information is extracted from the Report "Matilija Dam, Reservoir Operation and Modification Cost Study April 1975" by the Ventura County Public Works Agency, Flood Control District, and Casitas Municipal Water District (CMWD) (see Reference 2).

"The operation criteria for Matilija Reservoir used in this study was developed by the CMWD and became effective on December 14, 1970. The reservoir is operated as follows:

1. On November 1 of each year, reduce reservoir level to the minimum pool of 533 acre-feet.
2. Store excess flows in Matilija only when discharge at diversion canal exceeds 520 cfs.
3. Release from Matilija such that flow in diversion canal is at least 50 cfs.
4. Draw reservoir to minimum pool of 533 acre-feet as soon as possible after storm.
5. On April 1 of each year, allow reservoir level to increase to around 1,000 acre-feet for emergency summertime storage."

k. Watershed

The drainage area is about 55-square-miles of steep, sparsely covered land comprising all of the drainage of Matilija Creek from about 0.4 mile above its confluence with the North Fork of Matilija Creek. The drainage rises from 1,095 foot elevation at the site to 6,003 feet at Monte Arido. The drainage is very fan-shaped, dividing into two major tributaries and numerous sub-tributaries.

l. Instrumentation and Monitoring

Installed instrumentation includes survey plates on the surface of the dam, six deformation meters in the abutments (Carlson meters attached to anchored pipes) and three measuring plates at the slip plane. The schedule of reading and submittal to the Division of Safety of Dams is shown on the following page:

<u>Instrument</u>	<u>Reading</u>	<u>Submittal</u>
Surface plates	Quarterly/ Semi-Annually	Quarterly/ Semi-Annually
Deformation meters	Weekly	Quarterly
Slip Plane plates	*	*

*The plates at the slip plane are submerged by the stilling basin pool. They are read occasionally to confirm or deny questionable readings of other instruments or other unusual circumstances.

The dam is attended daily as the operator lives on site. During high storage periods the outlet is frequently attended. The Division of Safety of Dams inspects the dam twice a year.

Drawings showing typical installed instrumentation are shown in Appendix 2. Some of these surface monuments have been removed or replaced since these drawings were made. The results of readings over the years are discussed in Section 3 General History.

3. GENERAL HISTORY

Matilija Dam was designed by the Donald R. Warren Company of Los Angeles in 1946. The design method was stated to be by use of "Fowler's Curves" (Fowler, E. H. "A Graphical Method for Determining the Stresses in Circular Arches by the Cain Formulas" Trans. ASCE Volume 92, 1928, p. 1512). Arch action alone is considered in this analysis, an adequate method for a thin arch dam of moderate height. Waterload and temperature drop were considered. A summary of the computations is included as Appendix 4. As computed, compressive stresses ranged as high as 1,043 psi; no tensile stresses were reported.

Independent analyses by the California Division of Water Resources was by Perkins' Method (Subsequently published as ASCE Paper No. 2559, Transactions, Vol. 118, 1953, p. 725). This method also only considers horizontal arch action and does include temperature drop. Approval of the State of California for this construction was conditioned upon two requirements:

1. After excavation the arches would be redesigned to a maximum stress of 800 psi, and
2. Shear stresses at the base would be minimized.

This second requirement virtually directed the use of the sliding joint in the base.

Difficulties were experienced during construction when unsound rock was discovered high on the left abutment. Construction was shut down by State order on April 23, 1947, while several eminent consultants studied the problem. Construction remained shut down until May 24, when further excavation was reviewed. Consultants for the State were Fred C. Herrmann, Engineer of San Francisco; Walter Huber, Engineer of San Francisco; and Chester Marliave, Geologist.

Dr. John Buwalda, Geologist, and William P. Creager, Engineer, consulted for the Warren Company. Charles P. Berkey, Geologist of Columbia University, and Thomas L. Bailey, Geologist, of Ventura, consulted for Ventura County. The dam was completed uneventfully.

By 1960 progressive upstream movement of monuments and cracking of the concrete was suggesting to observers that alkali-aggregate reaction was taking place. In 1964 the Supervisor, Safety of Dams, of the State of California, requested the owner to investigate the condition of the dam. The owner engaged the Bechtel Corporation for this investigation which resulted in the report "Review of Matilija Dam, February 1965" (Reference 2) which recommended the spillway be lowered and a program of inspection and monitoring be commenced.

8. Thermometers should be embedded in core holes.
9. Sonic testing of concrete should be done if core drilling indicated poor quality concrete.

The recommended concrete coring and testing was carried out and reported in "Matilija Dam Phase II Investigations", International Engineering Company, December 1975. Table 1 of this study "Laboratory Test Results" is reproduced in Appendix 6.

At the time of this writing (1978) there is a project in progress to remove the spillway bridge, to remove deteriorated concrete adjacent to the spillway notch cut in 1965 (above Elevation 1,095) and to put an additional outlet through the dam near the left abutment replacing the inoperable sluiceway. The removal of the deteriorated concrete further increases the spillway capacity of the dam.

4. ENGINEERING DATA

4.1 Geologic Conditions

a. Areal Geology

The dam is on the coastal flank of the Santa Ynez Mountains of the Transverse Range. The geologic structure is dominated by the overturned Matilija anticline, and bedding generally dips steeply to the northwest. Complex local folding and faulting is common in the area.

The Eocene Matilija formation underlies the dam. It is composed of comparatively massive sandstones interbedded with thin, closely fractured sandstone beds and weak shale beds. The shales are soft, closely fractured and subject to air slaking.

There are several major faults trending parallel or sub-parallel to the mountain range. The Santa Ynez fault, two miles north of the dam, is the closest. The San Andreas fault is about 25 miles to the north.

Maps showing faults and earthquake epicenters in the vicinity of the dam are shown on the following pages.


b. Regional Seismicity and Faulting

<u>Fault</u>	<u>Santa Ynez</u>	<u>San Cayetano</u>	<u>Big Pine</u>
<u>Maximum Credible Richter Magnitude (M)</u>	7.5	6.75	7.5
<u>Distance from Dam (mi/km)</u>	1½/2	5/8	13/21
<u>Peak Bedrock Acceleration (g)</u>	0.7	0.5	0.35
<u>Duration Bracketed Strong Motion, +0.05g (sec)</u>	32	23	28
<u>Predominant Period (sec)</u>	0.37	0.27	0.37
<u>Probable Sense of Motion</u>	dip slip, reversed	dip slip, thrust	left lateral


Reproduced from CDMG Fault Map of California 1975

Scale 1:750,000

MAP OF FAULTS IN THE VICINITY OF PROJECT



5-7



NOTE: Only the larger of overlapping events are shown

MAGNITUDE

-  4.0 TO 4.9
-  5.0 TO 5.9
-  6.0 TO 6.9
-  7.0 TO 7.9
-  8.0 OR GREATER

INTEGER—MAX. REPORTED INTENSITY



EXCERPT OF 1900 TO 1974
EARTHQUAKE EPICENTER MAP OF CALIFORNIA
CDMG-OPEN FILE REPORT 78-4 SAC

The San Cayetano fault is considered to be a part of the Arroyo Parida-More Ranch line of faulting. (Fault Map of California, Jennings, 1975)

Tectonic deformation is possible, but the potential is low.

c. Foundation

Dam - The dam foundation consists of sandstone and shale interbedded. The upper right abutment is moderately fractured sandstone and contains a weak shale seam. The remainder of the sandstone foundation is crushed to very badly fractured, the shales are sheared. A fault zone of gouge and crushed sandstone up to 150 feet thick underlies the right channel area. The foundation rock is generally weak.

The foundation was grouted to consolidate the bedrock and reduce leakage.

Sulphur springs were observed in the dam foundation.

d. Spillway

The overpour, center of dam, and stilling basin foundation are protected by a concrete apron.

e. Data

Geologic logs, sections and plan by Thomas L. Bailey, are in Appendix 3.

4.2 Design

a. Structural

As discussed in Section 3.1 the dam was originally designed and checked by suitable methods which are satisfactory, if conservative, to this day. That is, the simplified assumptions generally neglect strengths which the dam possesses such as the cantilever action, effects of gravity, and the shorter inclined arches which actually act to resist loads.

b. Hydrology and Hydraulics

The Bechtel Report of 1965 found the then existing spillway to be inadequate to pass a Probable Maximum Flood (PMF). Based on some broad judgments (Reference 2, pg. 4-5) Bechtel estimated the peak of the PMF to be between 70,000 and 80,000 cfs. This flow is discharged with 18.7 feet of head on the spillway notch installed in 1966 (Reference 2, pg. 2-1).

Because of the broad judgments involved it was decided for the Phase I report to recompute a PMF based on HMR No. 36 (see Appendix 1). The Probable Maximum Flood was computed from the Probable Maximum Precipitation using basin characteristics derived from "Generalized Standard Project Rain Flood Criteria for Southern California Coastal Streams" publication of the Hydrologic Engineering Center, March 1967. The hydrograph was computed using USCE program L228 as modified for use on the Department of Water Resources' computer.

This flood is passed without routing through the spillway notch under construction in 1978 with a reservoir surface elevation of 1,111.0. The flood peak is 76,108 cfs, approximately as estimated by the Bechtel Company. Spillway capacity is computed by weir formula $Q = CLH^{3/2}$. "C" is assumed as 3.2 from Table 5-3 "Handbook of Hydraulics", King and Brater, Fifth Edition. This computation is contained in Appendix 1.

4.3 Construction

The construction history is available in detail in the records of the Division of Safety of Dams and is summarized in Section 3. Reference 2, page V-4 refers to 28-day cylinder breaks averaging in the range of 4,500 to 5,000 psi. Several examples of concrete cylinder break reports of concrete placed in August of 1947 are included in the files of the Division of Safety of Dams. These 6 tests, covering 2 days' placement, average 4,532 psi.

4.4 Operation

Readings of dam movement as indicated by surface monuments and deformation meters are received and evaluated quarterly in the Division of Safety of Dams. An example of a reading transmittal and evaluation are shown in Appendix 2. At the present time several meters are out of service. The readings are plotted as "Deformation Vs Time" with "Reservoir Level Vs Time" available for comparison.

The submitted plots are not suitable for reproduction but are available in the files of the Division of Safety of Dams for inspection. The dam continues to deflect upstream presumably related to the alkali aggregate reaction.

5. VISUAL INSPECTION

5.1 General

A field inspection of the dam, appurtenant structures, reservoir area, and downstream channel in the vicinity of the dam was conducted on July 6, 1978. Photographs were taken.

5.2 Participants

Mr. Alex Sheydayi, Engineer, Ventura County Flood Control District

Mr. Roger Stephenson, Supervising Engineer, Regional Field Engineer, Division of Safety of Dams

Mr. J. F. Chaimson, Senior Engineer, preparer, Phase I Report, Division of Safety of Dams

5.3 Conditions Noted

a. Dam

The dam continues to crack both along lift lines and subparallel to the boundaries of the spillway notch which was cut in 1965 and enlarged in 1978.

b. Reservoir Level

Water was in storage approximately 42 feet below the spillway crest.

c. Leakage

No leakage was visible above the stilling basin.

d. Stilling Basin

With the discharges to the stream of turbid water little of the stilling basin could be seen. However, a rib of natural rock could be seen across the streambed a short distance below the stilling basin, thereby assuring that the stilling basin has not been undermined.

e. Outlets

Leakage from the riser structure was being passed through the 36-inch valve and bypassed to the stream. The new 42-inch outlet was under construction at the time of the inspection. A subcontractor for this blasting was at work, setting off two small trimming blasts during the inspection. The hole for the outlet was open through to the riser from the downstream face but not trimmed out to full diameter.

In event of a power outage, the outlets can be operated either with emergency power or manually.

f. Outlet Riser

The temporary meter riser installed in 1970 was found to be damaged, apparently buckled inward during releases this past winter. Mr. Stephenson informed Mr. Sheydayi that the riser should be replaced this year. (Subsequently confirmed by letter July 12, 1978.)

g. Releases

A small release of the natural inflow (estimated 5 cfs) was being made to the stream at the center sluiceway. This was for the purpose of lowering the reservoir for work in progress at the outlet and stream release.

h. Reservoir Condition

At the reported storage level, it could be seen that the reservoir level was shallow up to a point approximately 50 feet from the dam. Mr. Sheydayi reported that about 900 acre-feet of sand and gravel was deposited in the reservoir during the winter of 1977-1978, leaving only about 1,800 acre-feet of storage. There are no slide areas which threaten displacement of significant amounts of the reservoir. There are numerous slide areas in the drainage which threaten continued deposition of erosional material.

i. Attendance

The operator's house located on the road about 1,000 feet downstream of the dam is occupied although he is not in full-time attendance at the dam.

j. Hazard Classification

Matilija Hot Springs County Park is located just downstream of the dam. State Highway 33 would obviously be obliterated at the junction to the North Fork by failure of the dam.

k. Warning System

Mr. Sheydayi explained that no special or automatic downstream warning systems are in service because outlet releases are small in comparison to stream capacity and spillway flows are only a small part of the total flow in the Ventura River because of the contributions of other tributaries.

5.4 Conclusions of Visual Inspection

- a. The dam continues to deteriorate due to alkali-aggregate reaction within the concrete. The deterioration has not progressed to the point of invalidating the IEEO studies.
- b. The reservoir continues to be filled in by erosional deposits and may have a very limited useful life.




Photo No. 5.1
Dam and reservoir depositions.




Photo No. 5.2
Drainage area showing steepness
and erosional areas.




Photo No. 5.3
Left side of arch. Note cracking at
lift lines.



Photo No. 5.4
Center arch. Note crack pattern on
lifts and between lifts.




Photo No. 5.5
Downstream face above outlet. Note
cracking adjacent to notch and large
crack openings on lift joints.



Photo No. 5.6
Downstream face above and left of
outlet. Note cracking.




Photo No. 5.7
New 42-inch outlet under construction.



Photo No. 5.8
Outlet intake riser. Note damaged area.

6. CONCLUSIONS

The Flood Estimate and Spillway Analysis presented in Appendix I, shows that irrespective of the method of reservoir operation, the dam will safely pass the PMF with a freeboard of 27 feet.

Alkali-aggregate reaction is gradually destroying this dam. In the course of 30 years concrete strengths have been reduced from around 4,500 psi (Reference 2) to 3,445 psi in the upper 40 feet (Reference 5). The potential for continuing alkali-aggregate reaction in the entire dam has been shown to exist (Reference 5). Visual observations indicate continued cracking and expansion of cracked areas where confining pressures are relieved by remedial measures.

The deterioration of the dam is recognized by the owners and they retained IECO to evaluate the stress conditions of the dam using the latest analysis techniques (References 4 and 5). The conclusions of these analyses are that the dam is presently and for the near future, safe for use.

The reservoir is gradually filling with erosional depositions from the drainage area.

The owners also are cognizant of the siltation problem and have given it serious study. Prior to cutting the notch in the central portion of the dam in 1965, various alternatives were investigated including complete removal of the dam to Elevation 980.

In March 1974, the Ventura County Board of Supervisors authorized a study which considered both possible dam modifications and siltation. Six alternatives were investigated including destruction of the dam to Elevation 1040, four alternative operation schemes with various structural modifications, and complete clean-out of the reservoir debris deposited since 1948. A computer program was developed and used to predict storage lost to silt. The program predicted that the reservoir would not completely silt in until after the year 2000. The study concluded that a more economical alternative source of water is not available, and unless Matilija Dam is found to be unsafe, hazardous, or otherwise unfit for operation or storage of waters, its continued operation as a water conservation reservoir is in the best interests of the public (Reference 6).

7. RECOMMENDATIONS

1. The owners should continue the present program of close observation, both visually and instrumentally, to detect changes beyond the bounds of those used in the studies prepared by the International Engineering Company in August 1972 and December 1975, and the "Matilija Dam, Reservoir Operation Cost Study" of April 1975. (See References 4, 5, and 6).
2. Periodic testing of the concrete should be continued, including strength, petrographic and sonoscopic tests at intervals of 5 years or less as recommended in the August 1967 Bechtel Corporation Report "Review of Matilija Dam." (See Reference 3).
3. To maintain outlet capacity the intake riser should be repaired. This has been requested of the owner. The owner has filed and received approval from the California Division of Safety of Dams for replacement of the intake riser; construction is scheduled for the fall of 1979.
4. No further investigation is recommended at this time.

8. REFERENCES

- (1) "Recommended Guidelines for the Safety Inspection of Dams", Department of the Army, Office of the Chief of Engineers.
- (2) "Review of Matilija Dam", Bechtel Corporation, February 1965.
- (3) "Review of Matilija Dam", Bechtel Corporation, August 1967.
- (4) "Matilija Dam, Stress Investigations", International Engineering Company (IECO), August 1972.
- (5) "Matilija Dam, Phase II Investigation", IECO, December 1975.
- (6) "Matilija Dam, Reservoir Operation and Modification Cost Study", Ventura County Flood Control District, Casitas Municipal Water District, April 1975.

9. APPENDIXES

- (1) Flood Estimate and Spillway Analysis for Matilija Dam, J. F. Chaimson, June 1978.
- (2) Movement Records and Instrumentation Installation.
- (3) Geology Logs.
- (4) Design Summary by Donald R. Warren Company.
- (5) Drawings.
- (6) Concrete Test Reports.

APPENDIX 1

Flood Estimate and Spillway Analysis
for Matilija Dam, J. F. Chaimson, June 1978

STATE OF CALIFORNIA
 THE RESOURCES AGENCY
 DEPARTMENT OF WATER RESOURCES
 Division of Safety of Dams

1. Dave Wong
 2. File


FLOOD ESTIMATE AND SPILLWAY ANALYSIS

Name of Dam MATILIA Type of Dam CONCRETE ARCH Dam No. 86
 County VENTURA Hazard Class IV Total Class Wt. 32
 Located on MATILIA CK Tributary to VENTURA RIVER

I. DRAINAGE BASIN
 1. Drainage Area - Sq. Mi. 55
 2. Impaired? NO
 3. Mean Elevation 3500'
 4. Mean Latitude 34°32.5'
 5. Mean Longitude 119°24'
 6. Annual Precip. - In. 31
 7. Elevation Index N/A*
 8. Cover Factor, C N/A*

II. DAM AND RESERVOIR
 1. Reservoir Area @ S/W-Ac 86 ①
 2. Res. Capac. to S/W-AF 1800 ②
 3. Surcharge Storage - AF NOT DETERMINED ③
 4. Spillway Crest Elev. 1095'
 5. Dam Crest Elevation 1138'
 6. Total Freeboard 43'
 7. Max. Storage Level 1095'
 8. Gated? NO
 9. Spillway Rating Q = C L H^{3/2}

① PER 1948 TOPO ② PER 1978 ESTIMATE ③ UPPER PARTS WILL NOT SUPPORT FULL WATER LOAD
 Sketch of Spillway, as per V.C.O.F.C.D. SH 2/13 Proj 4651 Date 8-2-77



Calculated by J.F. Chaimson Date Oct '78 Approved by _____ Date _____
Nov Project Engineer

III. FLOOD HYDROLOGY

1.	Flood Type	HMR36-PMP			
2.	Storm Precip.-In.	62.22			
3a.	Precip. Dur.-Hr.	72			
b.	K(J) Std. Dev.	-			
c.	Risk Level				
4.	Peak Inflow-cfs	76,108			
5.	Peak Inflow-csm	1384			
6.	Runoff - AF	138,219			
7.	Runoff - In.	47.12			
8.	Runoff Coeff.	76%			
9.	Div. Inflow-cfs	No			
10.	Routed?	No			
11.	Peak Outflow-cfs	-			
12.	Peak Outflow-csm	-			
13.	Resid. Freeboard	27.0'			
14.	Max. Res. Stage	1111.0'			
15.	Max. Spill. Cap.-cfs	Not Comp see note ③			
16.	Max. Spill. Cap.-csm	-			
17.	TC - Hr.	1.87 *			
18.	R/TC	0.8 *			
19a.	BASEL	0.80 *			
b.	Loss Rate				
20.	Check Adopted Flood				

REMARKS: * Basin characteristics from "Generalized S.P. Rain Flood Criteria, So Cal Coastal Streams" H.E.C. March 1967

STATE OF CALIFORNIA
THE RESOURCES AGENCY
DEPARTMENT OF WATER RESOURCES
Division of Safety of Dams

HAZARD CLASSIFICATION FOR FLOOD
ESTIMATE AND SPILLWAY ANALYSIS

Name of Dam MATILIA Type of Dam CONC ARCH Dam No. 86
County VENTURA Located on MATILIA CK

Hazard Class

		<u>Extreme</u>	<u>High</u>	<u>Moderate</u>	<u>Low</u>
Capacity <u>1800</u> A.F. (circle weight)		100,000 & Over 6	1,000-99,999 (4)	100-999 2	15-99 0
Height <u>133</u> Ft. (circle weight)		150 & Over 6	100-149 (4)	50-99 2	6-49 0
Estimated Evacuation (circle weight)	_____	1,000 & Over (12)	100-999 8	1-99 4	None 0
Potential D/S Damage (circle weight)		High (12)	Moderate 8	Low 4	None 0
Weight-Range	0-6 7-18 19-30 31-36				Total Class Weight <u>32</u>
Class	I II III IV				Class <u>IV</u>

Project MATILIA DAM NO 86 Sheet _____
 Feature HYDROLOGY Designed JFC Date 5-30-78
 Item Basin Characteristics Checked _____ Date _____

FROM "GENERALIZED S. P. R. F. CRITERIA FOR
 SO. CAL. COASTAL STREAMS"
 H. E. C. MARCH 1967

$$\begin{aligned}
 T.C. &= a(D.A. \times L.C.)^{.25} \\
 &= 0.4(55.0 \times 8.7)^{.25} \quad a = 0.4 \text{ from Ch 6} \\
 &= 1.87 \text{ hrs}
 \end{aligned}$$

$$R/TC = .8 \quad (\text{generalized in study})$$

$$R = 1.50$$

Project Matilija Dam No 86 Sheet _____
 Feature Hydrology Designed JFC Date 5-30-78
 Item HMR 36 - PMP Checked _____ Date NOV 1978
REVISED

Longitude $119^{\circ} 24'$
 Latitude $34^{\circ} 32.5'$

1. Orographic PMP Index 6hr Jan - 10"
2. Basin width 10.6 mi
3. Adjustment factor - 100%
4. 6hr increments orographic PMP x %

table 5-5 p 85 Coast Range


6 Hr	1	2	3	4	5	6	7	8	9	10	11	12
%	100	78	63	52	44	37	31	26	22	18	14	11
in	10.00	7.80	6.30	5.20	4.40	3.70	3.10	2.60	2.20	1.80	1.40	1.10
	From Fig 4-12 6 hr convergence PMP = 3.0" From Fig 4-13 b											
%	115	45	31	23	19	16	14	13	12	11	11	11
in	3.45	1.35	.93	.69	.57	.48	.42	.39	.36	.33	.33	.33
Comb.	13.45	9.15	7.23	5.89	4.97	4.18	3.52	2.99	2.56	2.13	1.73	1.43
Acc'm.	13.45	22.60	29.83	35.72	40.69	44.87	48.39	54.37	56.93	59.06	60.79	62.22

Orographic	Convergence	Total
1hr P = $.20 \times 10.00 = 2.00''$	$.46 \times 3.0 = 1.38$	3.38''
3hr P = $.54 \times 10.00 = 5.40''$	$.85 \times 3.0 = 2.55$	7.95''

PRECIPITATION DEPTH-DURATION-FREQUENCY CURVE

NAME OF DAM MATILUA No 86

CALCULATED BY JFC DATE 11-7-78



Project MATILISA Sheet _____
 Feature HYDROLOGY Designed JFC Date 11-8-78
 Item RAIN INCREMENTS Checked _____ Date _____

TIME	PRECIP	INCR	TIME	PRECIP	INCR	TIME	PRECIP	INCR
1	3.38	3.38	25		.95	49	54.74	.37
2	5.76	2.38	26		.94	50		.37
3	7.88	2.16	27		.92	51		.36
4	9.84	1.95	28		.91	52		.36
5	11.69	1.84	29		.90	53		.35
6	13.45	1.76	30		.89	54		.35
7	14.92	1.47	31		.88	55		.35
8	16.32	1.40	32		.87	56		.34
9	17.66	1.34	33		.86	57		.34
10	18.96	1.30	34		.86	58		.33
11	20.21	1.25	35		.85	59		.33
12	21.43	1.18	36		.84	60		.33
13	22.61	1.16	37		.83	61		.32
14	23.76	1.15	38		.83	62		.32
15	24.89	1.13	39		.82	63		.32
16	25.99	1.10	40		.81	64		.31
17	27.07	1.08	41		.80	65		.31
18	28.13	1.06	42		.80	66		.31
19		1.04	43		.79	67		.30
20		1.02	44		.79	68		.30
21		1.01	45		.78	69		.30
22		.99	46		.77	70		.29
23		.98	47		.77	71		.29
24	34.13	.96	48	54.37	.76	72		.29

$$\text{Slope}_{1-6} = \frac{\log 13.45 - \log 3.38}{\log 6 - \log 1} = .770808$$

1 hr Intercept

line₁₋₆ P_i = 3.38


$$\text{Slope}_{6-48} = \frac{\log 54.37 - \log 13.45}{\log 48 - \log 6} = .671735$$

log P_i = log P₄₈ - .671 (log 48)
 line₆₋₄₈ P_i = 4.032554

$$\text{Slope}_{48-72} = \frac{\log 62.22 - \log 54.37}{\log 72 - \log 48} = .332615$$

log P_i = log P₇₂ - .332 (log 72)
 line₄₈₋₇₂ P_i = 15.002145


Project MATILJA DAM No 86 Sheet _____
 Feature SPILLWAY CAPACITY Designed JFC Date 5-30-78
 Item _____ Checked _____ Date Rev Nov 78



$$Q = C L H^{3/2}$$

C = 3.2 Ref Table 5-3 Kings' 5th Ed

W.S.el.	Q ₃₆₀	Q ₄₂	Q ₄₃	Q _{TOTAL}
1110	66,925	—	—	66,925
1120	144,000	4,250	—	148,250



MATILIJA DAM NO 86
 HYDROGRAPH COMPUTATION PROGRAM L228
 CHAIMSON REVISED OCT 1978

ISTA	NHT	NUHQQ	NCLRK	IPNCH	QRCSN	EXTA	RTIMP		
0	1	0	0	1	0	1.50	0		
DA	TR	TP	CP	TC	RTIOR	RTIOL	RCVRY	E	RCLRK
55.00	60.00	0	0	1.87	1.00	4.00	0	.70	1.50
		1.70	.541	1.87					1.50
UNGR NQ= 10	TR=	60.00	MINS	SUMQU=	35400	VOL=	35475		

PMP FLOOD

HR	NP 72 MIN	BASEL .80 RAIN	DELTAL 0 LOSS	STARTQ 0 EXCESS	STORM 0 UNIT HG	SPFE 0 RECSN	PMS 0 FLOW	TRSPC 0	TRSDA 0
1	0	.2900	.2900	-0.0000	4889	0	-0		
2	0	.2900	.2900	-0.0000	11313	0	-0		
3	0	.3000	.3000	-0.0000	9637	0	-0		
4	0	.3100	.3100	0	4818	0	-0		
5	0	.3100	.2988	.0112	2409	0	55		
6	0	.3200	.2931	.0269	1205	0	258		
7	0	.3300	.2876	.0424	602	0	619		
8	0	.3300	.2763	.0537	301	0	1055		
9	0	.3400	.2716	.0684	151	0	1507		
10	0	.3500	.2669	.0831	75	0	1980		
11	0	.3600	.2623	.0977		0	2477		
12	0	.3700	.2579	.1121		0	2984		
13	0	.7600	.4118	.3482		0	4577		
14	0	.7700	.3925	.3775		0	7668		
15	0	.7900	.3785	.4115		0	10579		
16	0	.8000	.3623	.4377		0	12581		
17	0	.8100	.3476	.4624		0	14069		
18	0	.8300	.3369	.4931		0	15286		
19	0	.8400	.3242	.5158		0	16376		
20	0	.8600	.3151	.5449		0	17385		
21	0	.8700	.3041	.5659		0	18340		
22	0	.8900	.2962	.5938		0	19256		
23	0	.9100	.2888	.6212		0	20170		
24	0	.9400	.2838	.6562		0	21151		
25	0	.9600	.2769	.6831		0	22191		
26	0	.9900	.2723	.7177		0	23258		
27	0	1.0200	.2677	.7523		0	24373		
28	0	1.0600	.2650	.7950		0	25582		
29	0	1.1000	.2622	.8378		0	26912		
30	0	1.1500	.2608	.8892		0	28377		
31	0	1.1800	.2561	.9239		0	29904		
32	0	1.3000	.2645	1.0355		0	31724		
33	0	1.4000	.2686	1.1314		0	34230		
34	0	1.7600	.3037	1.4563		0	38365		
35	0	1.9500	.3129	1.6371		0	44579		
36	0	2.3800	.3444	2.0356		0	52529		
37	0	3.3800	.4198	2.9602		0	65277		
38	0	2.1600	.2895	1.8705		0	76108		
39	0	1.8400	.2486	1.5914		0	74174		
40	0	1.4700	.2052	1.2648		0	64795		
41	0	1.3400	.1869	1.1531		0	55551		
42	0	1.2500	.1735	1.0765		0	48259		
43	0	1.1600	.1608	.9992		0	43108		
44	0	1.1300	.1544	.9756		0	39415		
45	0	1.0800	.1464	.9336		0	36840		
46	0	1.0400	.1397	.9003		0	34908		
47	0	1.0100	.1342	.8758		0	33324		
48	0	.9800	.1290	.8510		0	32102		
49	0	.9500	.1240	.8260		0	31062		
50	0	.9200	.1192	.8008		0	30111		
51	0	.9000	.1154	.7846		0	29237		
52	0	.8800	.1118	.7682		0	28479		
53	0	.8600	.1083	.7517		0	27812		
54	0	.8500	.1059	.7441		0	27231		
55	0	.8300	.1026	.7274		0	26727		
56	0	.8200	.1003	.7197		0	26261		

← Qp

57	0	.3000	.0972	.7028	0	25811
58	0	.7900	.0951	.6949	0	25368
59	0	.7800	.0930	.6870	0	24972
60	0	.7700	.0910	.6790	0	24634
61	0	.3700	.0538	.3162	0	22590
62	0	.3600	.0524	.3076	0	18277
63	0	.3500	.0510	.2990	0	14559
64	0	.3500	.0506	.2994	0	12591
65	0	.3400	.0493	.2907	0	11535
66	0	.3300	.0479	.2821	0	10889
67	0	.3200	.0466	.2734	0	10414
68	0	.3200	.0463	.2737	0	10067
69	0	.3100	.0450	.2650	0	9819
70	0	.3000	.0437	.2563	0	9577
71	0	.3000	.0434	.2566	0	9359
72	0	.2900	.0421	.2479	0	9175
73	0				0	7796
74	0				0	4873
75	0				0	2426
76	0				0	1202
77	0				0	591
78	0				0	285
79	0				0	133
80	0				0	57
81	0				0	19
TOTAL		62.1500	15.0253	47.1247	35400	0 1668196

$$\frac{47.12}{62.15} = 76\% \text{ runoff}$$


$$\frac{47.12}{12} \times 55 \times 640 = 138,219 \text{ Acrefeet runoff}$$

∴ routing in consequential



$$\frac{Q_p}{D.A} = \frac{76,108}{55} = 1384 \text{ csm}$$

APPENDIX 2

Instrumentation Installation 1965
Data Transmittal 1978
Data Review 1978



PLAN



NOTES

1. The only plates shown on this drawing are those which have been surveyed long enough and frequently enough to yield meaningful data on the behavior of the dam.

LEGEND

○ Soniscope Testing performed by Bechtel.

□ Soniscope Testing performed by PCA.

DATE	ISSUED FOR	BY	CHKD BY
1967	Aug 1967 Report	M. MORRIS	S. BROWN
BECHTEL CORPORATION			
SAN FRANCISCO			
COUNTY OF VENTURA DEPARTMENT OF PUBLIC WORKS FLOOD CONTROL DISTRICT			
REVIEW OF MATILIJIA DAM—1967			
DAM MOVEMENT PLATE LOCATIONS AND ELEVATIONS			
NO. 5716	REV. 5716-67-3		

county of ventura

Director
Arthur E. Goulet

July 19, 1978

Deputy Directors
Donald A. Betlach
Road Department
T. M. Morgan
Engineering Services
G. J. Nowak
Flood Control/Water Resources
Donald B. Perry
Management Services
E. D. Shinavar
Construction Services

Mr. James J. Doody, Chief
Division of Safety of Dams
State Department of Water Resources
P.O. Box 388
Sacramento, California 95802

Subject: MATILIJA DAM-REPORT OF INSTRUMENT READINGS,
FLOOD ZONE I


Dear Mr. Doody:

Enclosed for your information are updated copies of Abutment Yield Measurement Data at subject location for the period April 5, 1978 through July 3, 1978, and graphs of reservoir elevation versus time, deformation versus time, and survey data showing deflection of the face targets.

You will note that the modification work on the dam has removed two face targets and the survey will now include a total of ten targets. In our last report, we indicated that four strain gages were not operating. One instrument has now been repaired and the remaining three will be examined when the modification and cleanup work is completed.

Very truly yours,

Gerald J. Nowak, Deputy Director
Flood Control and Water Resources Department

by 
Gerald D. Bickel
Supervising Hydrologist

Enclosures

GDB:ggh

INSTRUMENTATION DATA REVIEW

Name of Dam Metilija Dam No. 85

Date Period Second quarter of 1978

Significant Observations and Remarks:

Stage

The water level in the reservoir fluctuated between three and 11 feet below the certified spillway elevation of 1095 feet until late June on June 20, the owner emptied the reservoir.

Abutment Yield Deformations

The deformations confirmed the continuation of past trends in the right abutment instruments.

With the completion of the modification and clean up work, repair of the inoperable strain gages should shed light upon the compression of 0.128-inch in the last year at DH-1L and the unusual compression double the past trends at DH-2L.

Face Targets

Except for the contradiction movement at targets 5 and 6, the upper targets, including 1, 10, 11, and 12 moved upstream and toward the left abutment at an increasing annual rate. The maximum 25mm. upstream and 10mm. left deflection occurred at target 10 in the left corner of the spillway.

General Conditions Indicated by the Data:

The target data indicated an increase in the left and upstream movement of the upper face of the dam.

APPENDIX 3


Geology Logs, Section and Plan
by Thomas L. Bailey

APPENDIX 4

Design Summary
Donald R. Warren Company

APPENDIX 5

Selected Drawings, Matilija Dam



LEGEND


[Pattern]	SOLID SANDSTONE	[Pattern]	FRACTURED SHALE
[Pattern]	SLIGHTLY FRACTURED SANDSTONE	[Pattern]	CRUSHED SHALE
[Pattern]	MODERATELY FRACTURED SANDSTONE	[Pattern]	SHALY FAULT GOUGE
[Pattern]	BADLY FRACTURED SANDSTONE	[Pattern]	SHALY SANDSTONE (SOLID)
[Pattern]	SHATTERED SANDSTONE	[Pattern]	CONCRETE OF DAM OR APRON
[Pattern]	CRUSHED SANDSTONE	[Pattern]	GROUT FILLED CRACK
[Pattern]	SOLID SHALE	[Pattern]	NO CORE RECOVERED

NOTE: PERCENTAGE OF SPACE (BETWEEN NUMBERED DEPTHS ON RIGHT SIDE OF CORE) LEFT BLANK (NC) SHOWS PERCENTAGE OF CORE NOT RECOVERED.


[Pattern] CORE OF ANGULAR ROCK FRAGMENTS (CAVINGS) CEMENTED BY GROUT (ONLY IN HOLES REDRILLED AFTER GROUTING).

VENTURA COUNTY FLOOD CONTROL DISTRICT
 ZONE ONE
DETAIL LOGS OF CORE HOLES
MATILJA DAM
 PREPARED BY THOMAS L. BAILEY, CONSULTING GEOLOGIST
 DECEMBER 1948
 VERTICAL SCALE 1" = 5'
 (NO HORIZ. SCALE)


M. D.
 2157/1103




CORE HOLE 8-C
SCALE 1"=10'



CORE HOLE 6-E
SCALE 1"=10'



CORE HOLE 9-G
SCALE 1"=10'



CORE HOLE 16-K
SCALE 1"=10'

H. D.
2157 11103

VENTURA COUNTY FLOOD CONTROL DISTRICT
ZONE ONE


MATILIJA DAM
TYPICAL CROSS SECTIONS
SHOWING STRUCTURAL INTERPRETATION
FROM CORE HOLE AND SURFACE DATA

BY THOMAS L. BAILEY
Drawn February 7, 1949


86

2315

UTHWEST - RIGHT ABUTMENT



FAULT ZONE






D 2 3 1 4 / 0 1

ASSUMPTIONS FOR CALCULATIONS

F. EARTHQUAKE FORCES: 10% of Gravity
 Increase in Water Pressure 10%
 Arches are figured for Earthquake Forces acting parallel to Canyon.
 For Earthquake Forces acting crosswise to Canyon, the Dam is assumed to act mainly as a Shear Wall, with Arch Action of minor importance.

G. METHODS OF CALCULATION:
1. ARCHES AT EL. 1051 AND ABOVE are constant thickness, circular arches, and have been figured according to Fowler's Curves.
2. ARCHES AT EL. 1041, 1011 and 981 are analyzed on Calculation Sheets C-2, C-3 and C-4 respectively according to the Theory of Elasticity, using the following Formulas, based on locating Origin at the Elastic Center:
 Location of Elastic Center: $e = \frac{2R^2}{3t}$
 Lateral Thrust at Elastic Center: $H_0 = \frac{M_0}{e}$
 Moment at Elastic Center: $M_0 = \frac{P_0}{2}$
 where: $P_0 = \sum y^2 + \sum z^2 \cos^2 \alpha + n \sum z^2 \sin^2 \alpha$
 $C_x = \sum \frac{y^2}{R}$
 $D_x = \sum \frac{y^2}{R^2} M_0$
 $D_z = \sum \frac{y^2}{R^2} M_0 - (n-1) \sum (\frac{1}{2} \sin^2 \alpha \cos^2 \alpha \sum P_0 y) + \sum (\frac{1}{2} \cos^2 \alpha \sum P_0 z) + n \sum (\frac{1}{2} \sin^2 \alpha \sum P_0 z)$
 $n = 2.4$ to agree with Fowler's Curves
 $M_0 = 0.5 H_0 t$ where $H_0 = 0.625 R h$ (See Creager, *Int'l. & High* p. 42)
 Extreme Fiber Stress = $p = \frac{M_0}{R^2} \pm \frac{P_0}{R}$
 where: $p = \frac{M_0}{R^2}$ for extrados }
 $p = \frac{M_0}{R^2}$ for intrados }

3. ARCHES AT EL. 1051, 1031, 1021, 1001, 981 & 971 are analyzed by determining the statically indeterminate quantities from the following formulae:
 $y_0 = C_y y_0$
 $M_0 = C_M M_0$
 $H_0 = C_H H_0$
 The coefficients C_y, C_M and C_H are interpolated between the known values for arches at El. 1061, 1041, 1011 and 981. As will be seen from the graph below, the geometrical determinants $\sum y^2, \sum z^2, \sum yz$ for the arches in question vary so regularly that such interpolation is allowable with negligible error. Note: Length of fillet in all cases is $\frac{1}{2}$ of the total length of arch.
4. BELOW EL. 971 no arch action can be expected, because of resting on nearly rock. Stability of this portion has been investigated as a cantilever, using the thinnest section at Sta. 9+35.



H. SIGN CONVENTION
 Ordinates and Angles: 
 Deformations: 
 Moments and Thrust: 

I. NOMENCLATURE (See also Arch sketches on Calculation Sheets C-2, C-3 and C-4)
 α refers to angles on δ of Arch
 β refers to angles on extended δ of constant thickness Arch
 $H_0 = 0.625 \times R \times h$ (in kips)
 t = head below El. 1137 in feet
 $I = \frac{1}{12} \times$ Moment of Inertia of Arch Section in ft^4
 R_0 = Radius for Extrados in feet
 R_1 = Radius for Intrados in feet
 R_2 = Radius for δ of Constant Thickness portion of Arch in feet
 R_3 = Radius for δ of Fillet portion of Arch (average radius) in feet
 R_4 = Radius for Intrados of Fillet in feet
 Δs = Length of Arch Element
 δ = Thickness of Arch at any point
 t_0 = Thickness of Arch at Crown
 t_1 = Thickness of Arch at Abutment
 $\Delta x = t_0 - t_1$
 z = Radius with origin at Elastic Center
 y = Ordinate with origin at Elastic Center
 y_0 = Ordinate with origin at Crown
 2θ = Total Included Angle on Intrados


A. WATER LOAD AND TEMPERATURE STRESSES
 Concrete modulus = 3,000,000 lbs./sq. in.
 Creep = 1.0
 Shrinkage = 0.0005
 When earthquake and other forces are included, allow 33% more
C. TOTAL HEAD OF WATER is figured up to El. 1137
D. SPILLWAY CAPACITY: 60000 Cu.Ft./Sec. Net crest length of Intrados = 585' El. 1137'
 Average Crest Line at El. 1126'
 Total Head above Crest = 11'
 Design Velocity Head $(\frac{V^2}{2g}) = 2.52 \times 2 = 5.04'$
 Height of water above Crest = 5'
 Check on Spillway Capacity $3.0 \times 585 \times 9 \times 60000$ Cu.Ft./Sec.
E. TEMPERATURE VARIATION
 $F = 0.9$ in degrees Fahrenheit above and below closing temperature which is assumed to be the mean annual.
 Elastic Modulus = 1500000 lbs./sq. in. has been assumed, taking Temperature Expansion Coefficient for Concrete $C_r = 0.000055$

SUMMARY OF ARCH ANALYSES


Arch No.	Head below El. 1137	Radius Extrados R_0	Radius of Crown R_c	Thickness of Arch t_0	Total Arch Length 2θ	Cos α of Abut.	Elastic Cen. Dist. from Crown e	Arch Rise $3e$	For Water Load					For Temperature Drop					For Water Load & Temp. Drop											
									H_0 KIPS	M_0 Ft.-KIPS	M_1 Ft.-KIPS	M_2 Ft.-KIPS	M_3 Ft.-KIPS	Crown F_0 Ft.	Abutment F_1 Ft.	F_2 Ft.	F_3 Ft.	F_4 Ft.	Crown F_0 Ft.	Abutment F_1 Ft.	F_2 Ft.	F_3 Ft.	F_4 Ft.							
1101	36	290	276	8	128°43'	0.290			+590	+500	+45	+638	21°	0.3°	157	-31.4	+0	-1	20	+20	+600	+489	+42	+628						
1091	46	276	273.5	9	130°15'	0.328			+682	+58	+75	+748	20°	0.4°	202	-42.4	+1	-2	22	+24	+693	+579	+43	+770						
1081	56	276.5	271.5	10	129°10'	0.367			+785	+62	+85	+825	19°	0.6°	250	-62.0	+2	-3	24	+28	+760	+609	+53	+845						
1071	66	275.5	270	11	125°45'	0.405			+885	+74	+105	+951	18°	0.8°	302	-78.4	+3	-4	26	+28	+798	+633	+55	+915						
1061	76	274.5	268.5	12	121°30'	0.426	0.444	137.3	47.2	1330	8.1	0	370	710	+844	+84	+155	+973	17°	12°	349	-109.8	+4	-15	28	+28	+858	+669	+52	+1001
1051	86	274	267.5	13	119°55'	0.411		128.5	42.5	1472	18.2	2	655	587	+915	+82	+169	+941	16°	21°	444	-151.0	+5	-24	35	+35	+985	+608	+534	+876
1041	96	273	266.0	14	119°52'	0.385		121.1	37.6	1638	33.1	255	988	562	+977	+89	+160	+767	15°	31°	550	-200.0	+6	-33	36	+36	+993	+571	+524	+803
1031	106	271.5	263.0	15.75	120°30'	0.391		119.0	34.6	1800	50.3	473	1547	563	+994	+92	+170	+770	4	44°	610	-202.0	+4	-30	36	+36	+1018	+536	+404	+708
1021	116	269.5	261.75	17.5	125°30'	0.398		115.5	32.1	1955	31.3	725	2230	980	+1006	+94	+160	+630	13°	51°	710	-267.0	+6	-34	37	+37	+1032	+420	+404	+669
1011	126	266.5	257.12	19.25	126°15'	0.381		108.6	28.73	2110	131.5	950	3025	1975	+1010	+91	+158	+516	2	61°	770	-310.0	+7	-35	40	+41	+1037	+343	+312	+657
1001	136	264.5	254.0	21	128°10'	0.365		103.5	25.9	2240	202	1130	4040	3515	+1012	+90	+156	+50	1	71°	830	-363.0	+8	-44	43	+46	+1043	+261	+243	+676
991	146	262.5	250.17	22.75	131°50'	0.327		97.2	23.4	2385	285	1510	5210	5160	+1006	+85	+155	+62	11	81°	890	-410.0	+9	-43	45	+50	+1038	+196	+190	+676
981	156	259	246.75	24.5	135°00'	0.287		90.7	21.4	2525	332	1825	6575	6875	+1001	+85	+152	+61	10	91°	950	-460.0	+9	-54	45	+51	+1034	+101	+147	+667
971	166	254.75	241.62	26.25	140°00'	0.225		83.5	19.0	2640	531	2150	8050	10300	+985	+77	+154	+64	10	101°	1010	-510.0	+9	-66	45	+60	+1021	+11	+81	+700



GRAPH FOR INTERPOLATION OF ARCH COEFFICIENTS



CANTILEVER ANALYSIS FOR SECTIONS BELOW ELEVATION 971





VENTURA COUNTY FLOOD CONTROL DISTRICT
 ZONE 1
MATILJA RESERVOIR



TOPOGRAPHY
 JANUARY 1948
 CONTOUR INTERVAL 5 FOOT
 BENCH MARK '955' (U.S.G.S.)
 ELEVATION 959.414

SCALE
 DRAWN BY: S.H.M.
 TRACED BY: S.H.M.
 CHECKED BY: S.H.M.

© SET BRASS CAPPED MONUMENT
 (UNLESS OTHERWISE NOTED)




T. 5 N. R. 23 W.




M. D. 29/28
 2/57/1094
 17700-32-33
 FOUND 1" PIPE IN ROCK MOUND

2220




GENERAL PLAN
Scale 1" = 20'

RIGHT ABUTMENT





RIGHT ABUTMENT THRUST BLOCK
SECTION STATION 6+16
Scale 1" = 20'


LEFT ABUTMENT



LEFT ABUTMENT THRUST BLOCK
SECTION STATION 0+00
Scale 1" = 20'



LONGITUDINAL PROFILE
(Along E of top Arch Ring)
Scale 1" = 50'



GRAVITY SECTION
SECTION STATION 3+00
Scale 1" = 50'




STATE OF CALIFORNIA
DEPARTMENT OF PUBLIC WORKS
DIVISION OF WATER RESOURCES
APPLICATION NO. 86
APPROVED AS TO SAFETY
SEPT 16, 1949
DATE
STATE ENGINEER

VENTURA COUNTY FLOOD CONTROL DISTRICT
ZONE ONE




MATILAJA DAM
GENERAL PLAN & SECTIONS
AS BUILT

REV. NO.	DATE	REVISION	MADE BY	CHK. BY	APP. BY

AS SHOWN
SCALE
DESIGN
DRAWN
CHECKER
DONALD R. WARREN CO.
ENGINEERS
LOS ANGELES SAN FRANCISCO
2-6-48
DATE
LA 46 1d
JOB NO.
AB-3
DRAWING NO.



DEVELOPED ELEVATION ON UPSTREAM FACE



REFERENCE DRAWINGS

5214-R-2	General Layout
5214-R-4	Reinforcement Steel for Concrete to be Removed
5214-R-5	Metalwork to be Removed from Pier No. 7
5214-R-8	Electrical Work

Approved	By	Chief Engineer
Approved	By	Chief FC Eng'r
Approved	By	Dir. of Pub. Wks.

ISSUED FOR CONSTRUCTION		DATE	BY	CHKD	ENGR	PROJ	CLERK
NO.	DATE	DESIGNED	MM	NWN	DRAWN	BOUMER	

BECHTEL CORPORATION
SAN FRANCISCO



COUNTY OF VENTURA
DEPARTMENT OF PUBLIC WORKS
FLOOD CONTROL DISTRICT
MATILUJA DAM - REMEDIAL WORKS

DAM CONCRETE TO BE REMOVED

JOB No.	DRAWING No.	REV.
5214	5214-R-3	0



- NOTES**
- See specifications for requirements concerning removal of concrete by blasting.
 - All embedded metalwork or reinforcement steel, whether shown or not, will be considered as part of the concrete to be removed.
 - See specifications for disposal area.
 - All structures and equipment shall be protected from damage at all times.
 - The District will maintain a pool of minimum elevation 1025. See specifications for more details.
 - For details of reinforcement in piers and bridge - See drawing 5214-R-4.
 - For details of metalwork to be removed from pier no. 7 - See drawing 5214-R-5.
 - Concrete to be removed above El 1120 other than piers and bridge is designated "Ogee Section."



SECTION
STA. 1+00
Scale: 1"=10'-0"

SECTION
STA. 2+00
Scale 1"=10'-0"

SECTION
STA. 3+00
Scale: 1"=10'-0"

NOTE—
Grout holes to be 10'-0" oc. along lines shown, alternate 10'-0" & 25'-0" deep. Min dia 1 1/2". Provide 3" std steel pipe thru masonry, upper end capped. Drilling inclination to be determined in the field by the Engineer.

△ Note: Sections are taken through a vertical plane radial to the top arch &

2227

STATE OF CALIFORNIA
DEPARTMENT OF PUBLIC WORKS
DIVISION OF WATER RESOURCES








APPLICATION NO 86
APPROVED AS TO SAFETY

SEPT 16, 1949
DATE


STATE ENGINEER

THIS DRAWING SUPERSEDES DRAWING S3
VENTURA COUNTY FLOOD CONTROL DISTRICT
ZONE ONE

				M. D.			2157 11096	
				MATILJA DAM		SECTIONS		
				DONALD R. WARREN CO. ENGINEERS		LA-46-1C JOB NO.		
				LOS ANGELES		SAN FRANCISCO		
				DESIGN J.B.H.		1-10-47		
				DRAWN G.A.F.		DATE		
				CHECKED R.B.		CALIF. REG. NO. 1160		
DATE	APPROVED BY	REV. NO.	DATE	REVISION	MADE BY	CRD. BY	APP. BY	
	V.C.F.C.D. ZONE ONE							



COPPER WATER STRIP
GALV. STEEL WATER STRIP SIMILAR
 No Scale



TYPICAL GROUT CONDUIT BOX
 No Scale

Note: For location of grout holes see drags FL-16, FL-17, FL-19

SECTION STA. 5+75

NOTE -

Grout holes to be 10'-0" ac. along lines shown, alternate 10'-0" & 25'-0" deep Min. dia. 1 1/2". Provide 3" std. steel pipe thru masonry, upper end capped. Drilling inclination to be determined in the field by the Engineer. Grouting System for typical contraction joint shown. Location of risers & grout boxes to be determined in the field by the Engineer.

STATE OF CALIFORNIA
 DEPARTMENT OF PUBLIC WORKS
 DIVISION OF WATER RESOURCES

APPLICATION NO. - 86
 APPROVED AS TO SAFETY

SEPT 16, 1949
 DATE

James H. ...
 CIVIL ENGINEER

THIS DRAWING SUPERSEDES DRAWING 54
VENTURA COUNTY FLOOD CONTROL DISTRICT
ZONE ONE

M. D.
 2157 1096

MATILIJIA DAM
SECTIONS

SECTION STA. 4+00

Note: For Apron Details See drag CC-13

SECTION STA. 5+00

REV. NO.	DATE	REVISION	MADE BY	CKD. BY	APP. BY
1		26-48 Rev'd SECTIONS TO AS BUILT H.G.T.			
2		7/17 Spillway Steps Bridge			

1" = 10'
 SCALE

DONALD R. WARREN CO.
 ENGINEERS
 LOS ANGELES SAN FRANCISCO

DESIGNED BY *J.B.H.*
 DRAWN BY *G.A.F.*
 CHECKED BY *R.B.*

1-10-47
 DATE

CALIF. REG. NO. 1188

LA-46-1C
 JOB NO.
CC-6
 DRAWING NO.

APPENDIX 6

Concrete Test Reports

- a. 1 cylinder break from construction February 1947
- b. Table 1 from Reference 5

COPY

WILLIAMS COMPANY
 820 SANTER STREET
 LOS ANGELES, CALIFORNIA

COPY

Lab. No. P120564
 Matilla Dam

CONCRETE MIXTURE DESIGN REPORT
 DATE February 13, 1947
 CONCRETE MIXTURE DESIGN NUMBER 47-41

NUMBER OF SACKS OF CEMENT PER CUBIC YARD OF CONCRETE 5.00
 ALLOWABLE 5.9
 W.C. Sand-Saticoy Rock Co. Irwindale, California
 GRAVEL W.C. Sand-Saticoy Rock Co. Irwindale, California
 PLANT Saticoy, California
 IRINDALE, CALIFORNIA
 % ORGANIC MATTER 1.6
 CLAY AND LOAM 1.6

FINE AGGREGATES - PER CENT PASSING TYLER STANDARD SIEVE

MATERIAL	%	NO. 4	NO. 8	NO. 16	NO. 28	NO. 48	NO. 100	F. M.
MATERIAL II	100.0	100.0	100.0	97.4	84.0	65.3	42.0	2.913
MATERIAL I	100.0	100.0	100.0	100.0	100.0	100.0	100.0	7.035
MATERIAL III	100.0	100.0	100.0	100.0	100.0	100.0	100.0	7.960
MATERIAL IV	100.0	100.0	100.0	100.0	100.0	100.0	100.0	8.796

COARSE AGGREGATES - PER CENT PASSING TYLER STANDARD SIEVE

MATERIAL	NO. 4	NO. 8	NO. 16	NO. 28	NO. 48	NO. 100
MATERIAL I	77.4	17.7	1.4			
MATERIAL II	77.4	17.7	1.4			
MATERIAL III	77.4	17.7	1.4			
MATERIAL IV	77.4	17.7	1.4			

AGGREGATE 1 2.593 2 2.667 3 2.720
 SPECIFIC GRAVITY (SATURATED AND SURFACE DRY)
 100.0 76.9 42.6 32.7 29.4 25.2 19.6 12.6 4.7 1.4 0.549

DESIGN FOR ONE CUBIC YARD OF CONCRETE (SATURATED AND SURFACE DRY PROPORTIONS)
 NOTE: THIS MIX TO BE USED ONLY WITH 0.3# TYPE 1 POZZOLITH ADMIXTURE PER SACK OF CEMENT. 2" to 3" slump 3000 P.S.I. at 28 days with type 2 cement.
 W/C = WATER CEMENT RATIO
 CF = CEMENT FACTOR IN SACKS OF CEMENT IN ONE CUBIC YARD OF CONCRETE
 AB = ABSOLUTE VOLUME OF ONE SACK OF CEMENT
 GM = SPECIFIC GRAVITY OF AGGREGATES IN ONE CUBIC YARD BATCH
 B = WEIGHT OF AGGREGATES IN ONE CUBIC YARD BATCH OF CONCRETE
 W = W.C. (W/C + 0.48) = 20.665

AGGREGATE 1 2.593 2 2.667 3 2.720
 W.C. 0.30 0.29 0.29
 TOTAL 26.999

AGGREGATE	% B	BATCH	SP. GR.	ABSOLUTE VOLUMES
1	30.0	1032.88	2.593	6.373
2	15.0	516.43	2.667	3.098
3	26.0	895.16	2.692	5.320
4	29.0	998.45	2.720	5.873
5	245.74	245.74		3.935
6	470.00	470.00		2.400
TOTAL				26.999

SATURATED AND SURFACE DRY PROPORTIONS FOR SACK BATCH
 RESPECTFULLY SUBMITTED:
 POUNDS 206.58
 POUNDS 103.29
 POUNDS 179.03
 POUNDS 199.69

WILLIAMS COMPANY
 820 SANTER STREET
 LOS ANGELES, CALIFORNIA

Table 1
LABORATORY TEST RESULTS

Boring/ Specimen Number*	Depth** (feet)	Bulk Specific Gravity	Static Young's Modulus (x 10 ⁶ psi)	Poisson's Ratio	Compressive Strength (psi)	Tensile Strength (psi)
1	61	2.34	4.14	.02	7,000	628
2	61	2.37	2.66	.05	5,945	628
3	61	2.37	3.77	.25	5,622	526
4	151		4.20	.04	6,637	611
5	151	2.36	4.06	.07	5,593	600
6	151		3.59	.09	5,951	574
B1	5	2.35	2.78	.06	4,384	1,271
B3	54		4.13			95
B4	66	2.31	2.72	.09	7,158	1,326
B5	79	2.35	3.62	.34	6,530	1,299
B5	91		3.87	.05	7,850	1,066
C3	42	2.35	1.13	.05	4,842	1,081
C4	56	2.36	2.55	.29	5,115	1,277
C7	112 (Rock)		2.24	.08	19,206	2,150
C8	141 (Rock)				19,957	
C9	167 (Rock)	2.61	2.19	.27	3,663	70
A2	38.5				2,505	760
A3	50	2.28	3.74	.03	5,726	1,104
A4	70	2.31	2.05	.10	4,928	1,318
A5	80	2.38	3.24	.06	6,138	1,007
A6	90	2.34	2.94	.30	7,098	1,544
A7	110		3.82	.14	7,537	978
A8	132	2.34	5.62	.21	7,728	1,339
A9	150	2.30	2.13	.07	6,388	1,406
A10	170	2.25	2.29	.10	5,732	1,069
A12	202 (Rock)		3.36	.19	5,221	

* Boring numbers 1 through 6 are horizontal and were drilled from the face of the dam. Borings A, B and C are vertical holes drilled from the crest of the dam (see Drawing HR-11-038).

** Depth is measured from El. 1128, crest of dam.